

Barcode Command Definition

F2 Start / Yes



\$W

F3 - Continuous



\$X

F4 - REDO / No



\$Y

ENTER / Continue



\$L

ESC / Abort



%A

ALT F4 - Close Message Window



\$B\$Y\$C

F7 - Enter Lot Number



%B

F8 - Enter Serial Number



%C

F9 - Enter User Name



%D

F10 - Enter Comment (Printing)



%E

Open Multimeter




\$D\$Z\$E

Open Signal Generator



\$D\$Y\$E

F5 - MUTE Signal Generator
(Sine Wave)



\$Z

Open Oscilloscope



\$D\$U\$E

Open FFT Analyzer



\$D%B\$E

Open RTA Analyzer



\$D%C\$E